# AUDU00133 Dulux Copper Patina Effect Effect

## Introduction

Part A
**690D0101**

## Description and Image

**Apply Dulux Copper Patina Effect** over Copper Effect to create the green patination of aged copper

## Features and Benefits

- Apply with brush, cloth or sponge
- Create the green patination of aged copper
- Clean brushes and equipment with water.

## Uses

Apply over Dulux Copper Effect. Best results are achieved if treatment begins as soon as the final coat of Dulux Copper Effect is touch dry (approx. 2 hours) and within 12 hours of application.

## Precautions and Limitations

Do not apply a clear sealer as this can remove or damage the effect, especially when new. The aged effect can be rubbed off when touched. We recommend natural weathering. On exterior surfaces, patination runoff may stain adjacent surfaces.

Do not apply in high humidity, below 10°c or above 30°c.

Please Note: Copper Effect treated with Copper Patina is a chemical reaction. Individual results may vary due to film thickness, methods used, time elapsed, ambient temperatures, substrate etc.

## Typical Properties

| Components | Number of Coats |
|---|---|
| 1 | 1-2 |

Touch Dry
**2 hours ( at 25 Deg C and 50% relative Humidity)**

Clean Up
**Water**

Clean Up Description
Do not pour solution down the drain.

Application Methods
**Brush**

Application Conditions

| | Min | Max | Recommended |
|---|---|---|---|
| Recoat Time (min/hours) | 2 hours | 12 hours | 2 hours |

## Application Guide

Application Procedure and Equipment

Apply over Dulux Copper Effect: Best results are achieved if treatment begins as soon as the final coat of Dulux Copper Effect is touch dry (2 hours) and within 12 hours of application. Prepare surfaces as per Dulux Copper Effect label. Apply Dulux Copper Patina solution by brush or muslin in a random pattern. The aged effect will continue to develop over days and weeks. A second coat can be applied if required. Do not apply a clear sealer as this can remove or damage the effect, especially when new. Individual results will vary due to the application method and environment. The patina can be rubbed off when touched.

## Health and Safety

| SDS Number | SDS Link |
|---|---|
| DLXGHSEN002636 | View SDS Link |

**Please refer to SDS Link. In case of emergency, please call 1800 220 770.**

## Transport and Storage

Pack A
**690D0101**

Flash Point
**N/A**

## Disclaimer

This Data Sheet is copyright to DuluxGroup (Australia) Pty Ltd and/or DuluxGroup (New Zealand) Pty Ltd (collectively, 'Dulux'). It may not be varied or altered without the prior written consent of Dulux, and if it is, Dulux has no responsibility or liability for those variations.

Unless Dulux has provided you with a customised, project-specific specification, this Data Sheet does not represent that any particular product or product system will be suitable for your project.

Any information provided in this Data Sheet is given in good faith and is believed by Dulux to be correct at the time of publication. Products and coating systems can be expected to perform as indicated in this Data Sheet, provided the substrate is in good condition, the coatings are applied by a suitably experienced and skilled applicator, and the preparation, application and maintenance is followed strictly as set out in this Data Sheet, and as recommended on the applicable Safety Data Sheets for the relevant products, available from www.duspecplus.com.au. Climatic conditions at application time can affect product suitability and performance.

The correct colour or colour match is the responsibility of the applicator. Colours will change over time and Dulux does not guarantee that the same colour newly mixed will match a colour applied earlier which has been subjected to weathering or other change elements. No product colour is guaranteed against colour change.

Where any liability of Dulux in respect of this Data Sheet cannot by law be excluded, Dulux's liability is limited, as permitted by law and at Dulux's option, to resupply of the relevant products or services or to reimbursing the cost of those products or services.

WHERE LEAD MAY BE PRESENT: The asset manager is responsible for verifying the presence of lead and determining whether to remove or encapsulate the lead. If lead is present, the work must be done in strict accordance with AS 4361 Parts 1 and 2 and Worksafe Australia guidelines.