

AUIN00679 Intergrain Hard Wax Oil

Introduction

Line Shade
702W0618

Description and Image

Intergrain Hard Wax Oil is a blend of waxes and oils that provides timber with a natural matt look. This hard wearing timber floor finish highlights the texture of timber – leaving a beautiful, tactile floor.



Features and Benefits

- Suitable for all interior timber
- Matt finish
- Hard wearing finish
- No sand maintenance
- No sealer required
- Formulated and tested for Australian conditions

Uses

Interior timber flooring, stairs, parquetry and cork.

Precautions and Limitations

Do NOT apply in temperatures under 10 °C or over 35 °C.

Performance Guide

Weather
Interior only

Water
Good for splashes and spillage

Abrasion
Good

Typical Properties

Gloss Level

<5% measured at 60 degrees

Colour

Clear

Number of Coats

2

V.O.C. Level

<530g/L

Meets GBCA V.O.C. Requirements?

No

Touch Dry

2 hours

Clean Up

Mineral Turpentine

Clean Up Description

Clean equipment and tools with mineral turpentine.

To avoid spontaneous combustion of contaminated application cloths, soak application cloths in water or immediately spread used application cloths flat in a cool, well ventilated area to dry completely before disposal. Do not scrunch up or place cloths on top of each other.

Application Methods



Brush



Roller

Application Conditions

Solids by Volume

33

Min

Max

Recommended

Recoat Time (min/hours)

4 hours

Theoretical Spread Rate (m²/L)

20

24

Typical Property Notes

Coverage

20 – 24m²/L depending on the porosity of the timber.

Dry times

Dry times are based on drying conditions of 25°C and 50% relative humidity. Drying times will be longer in conditions cooler than 25°C or more humid than 50% humidity.

Touch Dry: 2 hours.

Re-coat: Allow a minimum of 4 hours drying between coats.

Floors will take light foot traffic after 12 hours, and normal foot traffic after 3 days.

Full cure: Allow 7 days.

Replace furniture after 7 days.

Application Guide

Surface Preparation

New timber

Punch exposed nails below the surface. Note that holes and imperfections should be filled with timber putty after the first coat of Intergrain® Hard Wax Oil to match the putty colour with the coated timber colour.

Sand timber to an even, smooth surface. Vacuum and wipe to remove dust.

Previously coated surfaces

Clean surface with Intergrain Floor Cleaner and allow to dry.

Previous polyurethane coatings or varnishes need to be removed by sanding surface back to bare timber.

Previous coatings of Intergrain Hard Wax Oil can be recoated without sanding.

Application Procedure and Equipment

Surfaces to be coated must be dry and free from all dirt, dust, grease or polish.

Shake Intergrain Hard Wax Oil for 2 minutes to ensure contents are evenly mixed.

Apply a coat of Intergrain Hard Wax Oil to the timber with a brush, roller or cloth. Ensure the surface is evenly covered.

Once first coat is thoroughly dry, any grain raise can be removed by lightly sanding with 240 grit sandpaper, being careful not to sand through the coating.

When the first coat is thoroughly dry apply a second coat of Intergrain Hard Wax Oil following the application process outlined above.

Do NOT apply in temperatures under 10°C or over 35°C.

Staining

Stain bare timber after sanding using Feast Watson® Prooftint™ as per the application instructions.

To stain flooring, mix Feast Watson Prooftint with Feast Watson Prooftint Colour Reducer to allow time to evenly work the stain across the floor. Test the mixture rate on off-cuts of flooring to confirm the colour before staining the whole area.

Apply stain to the floor as per Feast Watson Prooftint instructions.

Allow 12 hours to dry before applying Intergrain Hard Wax Oil.

Maintenance

Allow Hard Wax Oil to cure for a minimum of 4 weeks before cleaning.

Regularly clean floors using Intergrain Floor Cleaner.

When surface requires an additional coat, clean with Intergrain Floor Cleaner and allow surface to dry fully. Apply one coat of Intergrain Hard Wax Oil as per application directions.

Health and Safety

SDS Number

DLXGHSEN005098

SDS Link

Using Safety Precautions

Refer to SDS

Please refer to SDS Link. In case of emergency, please call 1800 220 770.

Transport and Storage

Pack A

Intergrain Hard Wax Oil

Size:

Weight:

4L

3.92kg

Please refer to the Safety Data Sheet for full safety, health and transportation information.

Disclaimer

This Data Sheet is copyright to DuluxGroup (Australia) Pty Ltd and/or DuluxGroup (New Zealand) Pty Ltd (collectively, 'Dulux'). It may not be varied or altered without the prior written consent of Dulux, and if it is, Dulux has no responsibility or liability for those variations.

Unless Dulux has provided you with a customised, project-specific specification, this Data Sheet does not represent that any particular product or product system will be suitable for your project.

Any information provided in this Data Sheet is given in good faith and is believed by Dulux to be correct at the time of publication. Products and coating systems can be expected to perform as indicated in this Data Sheet, provided the substrate is in good condition, the coatings are applied by a suitably experienced and skilled applicator, and the preparation, application and maintenance is followed strictly as set out in this Data Sheet, and as recommended on the applicable Safety Data Sheets for the relevant products, available from www.duspecplus.com.au. Climatic conditions at application time can affect product suitability and performance.

The correct colour or colour match is the responsibility of the applicator. Colours will change over time and Dulux does not guarantee that the same colour newly mixed will match a colour applied earlier which has been subjected to weathering or other change elements. No product colour is guaranteed against colour change.

Where any liability of Dulux in respect of this Data Sheet cannot by law be excluded, Dulux's liability is limited, as permitted by law and at Dulux's option, to resupply of the relevant products or services or to reimbursing the cost of those products or services.

WHERE LEAD MAY BE PRESENT: The asset manager is responsible for verifying the presence of lead and determining whether to remove or encapsulate the lead. If lead is present, the work must be done in strict accordance with AS 4361 Parts 1 and 2 and Worksafe Australia guidelines.